



Kestrel[®] Pocket Weather[®] Meters

Operational and Storage Temperature Ranges

Kestrel 4000 Series Pocket Weather Tracker Temperature Ranges

°F	-40	-30	-20	-10	0	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220	230	240	250	257
°C	-40	-34	-29	-23	-18	-12	-7	-1	4	10	16	21	27	32	38	43	49	55	60	66	71	77	82	88	93	99	104	110	116	121	125
Sensors and data storage fully functional, AAA lithium batteries required for operation. Display nonoperational. Storage safe.					Unrestricted operations. Storage safe.															Unit may be exposed momentarily to take measurements, but storage or extended use may damage batteries, display or case. Display will temporarily black out with exposure.											

Kestrel 1000 to 3500 Series Pocket Weather Tracker Temperature Ranges

°F	-40	-30	-20	-10	0	10	14	30	40	50	60	70	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220	230	240	250	257
°C	-40	-34	-29	-23	-18	-12	-10	-1	4	10	16	21	27	32	38	43	49	55	60	66	71	77	82	88	93	99	104	110	116	121	125
Sensors fully functional but display nonoperational and battery power insufficient. Unit may be kept warm and exposed momentarily to take measurements. Storage safe.							Unrestricted operations. Storage safe.															Unit may be exposed momentarily to take measurements, but storage or extended use may damage batteries, display or case. Display will temporarily black out with exposure.									